



Use the Sidewalk Trail Maintenance module to identify and document the resolution of problems that can be a cause of significant liability to municipalities.

For all sidewalks, paths and trails

- Track the date each sidewalk/trail section is inspected
- Identify maintenance issues ranging from trip ledges and cracking to drainage and signs
- Sidewalk/Trail deficiencies are easily collected, either on foot, bike, golf cart, or any ATV or maintenance vehicle
- Send work order information directly to your repair crews' smart device or create hard copies with thumbnail maps and/or photos so your repair crews know the exact location and nature of the deficiency

BURNSIDE City of Smithville **BURNSIDE Mobile**
Work Order 2015-00004 Report date: 2015-02-17

Drainage - Catch basin


Service By: Request Generated By: Brian
Inspected On: 2015-02-17 17:17:05 Inspected By: Brian
Status: Assigned Assigned To: Brian Berry
Upon completion submit to: Gord Coupland
Description: Replace - west side at #56

Road Name: WELLINGTON ST Road ID: 341
From: SARAH ST Region:
To: FARSONS ST Class: 5

Notes

Completed By (Print): _____ Date: _____
Signature: _____

Page 1 of 1



Built on
Geocortex Essentials
Geocortex[®]